

PM 35



Features

- 1 .Large LCD
- 2 .Data hold
- 3 .With differential mode and record mode
- 4 .USB port
- 5 .Reset and data adjustment
- 6 .Low battery indication
- 7 .automatic power off



Measuring range	$\pm 35\text{kPa}$
Accuracy	$\pm 0.3\%\text{FSO}(25^{\circ}\text{C})$
Repeatability	$\pm 0.2\%$ (Maximum $\pm 0.5\%\text{FSO}$)
Linearity/hysteresis	$\pm 0.29\%\text{FSO}$
Response	Typical 0.5 s
Low battery indication	Yes
Up overload indication	Err1
Down overload indication	Err2
Operating temperature	$0\sim 50^{\circ}\text{C}$
Storage temperature	$-10\sim 60^{\circ}\text{C}$
Power supply	1.5V AAA battery*4
USB communication	Yes